





FIG. 1



200

FIG. 2



300

FIG. 3

FIG. 1 OF 2

Robert F. Scotti
Klarquist Sparkman et al
121 SW Salmon Street
Suite 1600
Portland, Oregon 97204
Telephone: 503/226-7391

Our Ref. No. 1011-59275
App No. Not yet assigned
Express Mail Label No. EL828140906U
For: A Method and Apparatus to Generate
A Wiring Harness Layout
Mailed: October 17, 2001




FIG. 4




FIG. 5




FIG. 6




FIG. 7







FIG. 8




902




904



906



908



910

FIG. 9

Robert F. Scotti
Klarquist Sparkman et al
121 SW Salmon Street
Suite 1600
Portland, Oregon 97204
Telephone: 503/226-7391

Our Ref. No. 1011-59279
App No. Not yet assigned
Express Mail Label No. EL828140906
For: A Method and Apparatus to Generate
A Wiring Harness Layout
Mailed: October 17, 2001




FIG. 10

Robert F. Scott
Klarquist Sparkman et al
121 SW Salmon Street
Suite 200
Portland, Oregon 97204
Telephone: 503/226-7391

Our Ref. No. 1011-59279
App No. Not yet assigned
Express Mail Label No. EL828140086US
For: A Method and Apparatus to Generate
A Wiring Harness Layout
Mailed: October 17, 2001




FIG. 11